If you are having trouble viewing, click here to view in browser.



## Product of the week!

Cam Repair Kit for Meritor 16 1/2" brakes with Fabricated Spiders



## M-K88:

Replaces: CQ67416, 08130611, E9079HD, and KIT8078A

For Use with Cams: M-4094-R/L, M-4095-R/L, M-4096-R/L M-3170-R/L, M-3171-R/L, M-3172-R/L

Speak with a salesperson at: 636-629-5800

**Visit our Website** 

Did you know we have a Buyer Login on our website where you can Check Availability, Delivery Time, Cross References,
Prices and Place your Orders Online? Ask us how!

BWP-NSI | #3 TLC Lane, St. Clair, MO 63077

<u>Unsubscribe neil\_dickhaus@nsihd.com</u>

<u>Update Profile |Constant Contact Data Notice</u>

Sent bysprings@nsihd.compowered by

